

Typical installation of load cell for floor scale kit

Base must be stiff enough as to not flex under load, which will cause inaccurate weight readings

1/2" mounting block tapped to 1/2-20, must be welded to platform

Cable to summing box

